



Cargo Sensor

INSTALL GUIDE




Directions

1




Clean mounting area with alcohol wipe.



Place sensor on ceiling. Mount at least 20 inches away from any wall.





Secure with included adhesive. Screw if desired.